



REPORT NO.: -M-24009/01

DATE: -04th July, 2024

CLIENT: Shrimati Shantaben Haribhai Gajera

VALID TILL: 31st December, 2027

VISUAL INSPECTION & BUILDING SAFETY ASSESSMENT REPORT FOR

GAJERA INTERNATIONAL SCHOOL

**SITUATED AT TP. NO.: 19 (KATARGAM), F.P. NO.: 68 PAIKEE SUB PLOT
NO.: 103 TO 108, 123 TO 128, SURAT**

MANAGED BY: SHRIMATI SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST

SMT. SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST


PRESIDENT _____

TRUSTEE _____

DR. POOJA CHHATRPATI
PRINCIPAL

GAJERA INTERNATIONAL SCHOOL
AMBOLI ROAD, KATARGAM, SURAT-4.
AFF NO: 430092 / SCHOOL CODE: 10082





ASSEMBLY AREA OF THE SCHOOL G+3 STOREY SCHOOL BUILDING



NO SIGN OF ANY LEAKAGE OR DAMPNES IN WALLS



SMT. SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST

PRESIDENT

TRUSTEE

19, RIVER DRIVE SOC., OPP DEEPA COMPLEX, ADAJAN ROAD, SURAT

DR. ANITA S. CHATTI
PRINCIPAL

GAJERA NATIONAL SCHOOL

AMROLI ROAD, KATARGAM, SURAT-4.

AFEE NO: 670002 / SURAT / 2007 / 10702

Email: shreeconsultingengineers@gmail.com

Mobile: +91 -6353172769


Adarsh



A WELL MAINTAINED PASSAGE. NO SPALLING OR CORROSION OF REINFORCEMENTS DETECTED FROM VISUAL INSPECTION



ADEQUATELY SIZED RCC MEMBERS, NO SIGNS OF ANY DEFLECTION OR DISTORTION.



SMT. SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST

PRESIDENT

TRUSTEE

Email: shrc consultingengineers@gmail.com

DR. P. M. SHARMA
 GAJERA INTERNATIONAL SCHOOL
 AMRGLI ROAD, KATARGAM, SURAT
 TEL: 91-79-2200111 SCHOOL CODE: 210001



NO VISIBLE CORROSION ON ANY M.S. MEMBERS

SMT. SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST

PRESIDENT _____

TRUSTEE _____

DR. ANURUPA BHATI
PRINCIPAL
GAJERA INTERNATIONAL SCHOOL
AMROLI ROAD, KATANGAM, SURAT-4.
AFF NO: 420992 | SCHOOL CODE: 10302





I, Harshal P Dalal, registered Structural Engineer with Surat Municipal Corporation having Registration No. TDO/ST.DR./377.

On receiving work order from trustees, I have visited the **GROUND + 3 STOREY R.C.C.** school building "**GAJERA INTERNATIONAL SCHOOL**" situated at T.P. NO.: 19 (Katargam), F.P. NO.: 68 PAIKEE SUB. PLOT NO.: 103 TO 108, 123 TO 128, Surat (MANAGED BY: **SHRIMATI SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST**) on 04th July, 2024. The building condition assessment carried out based on the visual inspection, the photographs were taken along with the primary data were collected in the presence of the clients.

The building was not designed by us. The clients has not provided any detailed structural drawings, working drawings, soil bearing capacity reports and material test reports done during the construction of the building and structural design calculations of the building for reference to the inspection. Hence, this present report has been prepared based on technical visual inspection, past experience and judgments.

From the site visit & photographs attached herewith, my observations are as below.

- The building is in working & in well maintained condition as on the date of inspection.
- The construction of the said school building appears to be a framed RCC building and it was constructed in the year 2003.
- There is no sign of any kind of deflections or distresses in any structural member.
- No structural cracks are seen in any structural member during visual inspection.
- There is no spalling of concrete anywhere found in the structure; hence there is no major corrosion of reinforcement of any structural member.
- There is no visible corrosion of any Mild steel member used in the building.

From the above observation, the **GROUND + 3 STOREY R.C.C. structure seems to be STABLE & SAFE UNDER LIVE LOAD AND DEAD LOAD IN NORMAL GRAVITATIONAL CONDITIONS FOR THE INTENDED USE OF SCHOOL BUILDING** as per my knowledge and belief provided that, it must be maintained at regular interval of time. **The validity of this certificate is from the date of issue which is 04th July 2024 to 31st December 2027**; the structure must be re-audited for stability after the end of this period.

Change or alteration of any kind i.e. change of purpose of use, alteration of type of machinery, alteration of wall positions and/ or any alteration of structural configuration, extension of floors or expansion of structure shall not be done without prior Permission in writing.

This certificate includes Structural aspect only. Any other aspects such as **Mechanical, Electrical, plumbing & Fire** are not in our scope. The building's compliance with requirements of B.U.C. certificate from SMC or any other approving agency is also beyond the scope.

Harshal P. Dalal

(CONSULTING STRUCTURAL ENGINEER)



SMT. SHANTABEN HARIBHAI GAJERA CHARITABLE TRUST

PRESIDENT

TRUSTEE